

MXA052 DIGITAL TEMPERATURE CONTROL -20 TO 100°C

MXA052 เครื่องวัดและควบคุมอุณหภูมิแบบดิจิตอล

FEATURES

- Power supply : 12VDC/max. 250mA.
- Max. load : 500 watts.
- Sensor temperature range : -20°C to +100°C.
- Display : 3 1/2 digits (0.1° display resolution).
- LED display, showing the following three items:
 - 1) Current temperature reading;
 - 2) Minimum temperature setting;
 - 3) Maximum temperature setting.
- Minimum and maximum thermometer.
- Can be set to the operation of relay.
- LED indication for power on/off and relay on/off.

CONNECTOR AND TUNNING

- 12V point is used for connected to the power supply 12VDC.
- SENSOR point is used for connected to the temperature sensor.
- NC, COM, NO point is connected to the equipment other.
- SW1 switch is used for select the showing on LED display. A position is showing the current temperature. B position is showing the maximum temperature setting. C position is showing the minimum temperature setting.
- J1 jumper is used for the operating.
- INV point is operation to the minimum temperature.
- NOR point is operation to the maximum temperature.
- VR1 is used to adjust the minimum temperature.
- VR2 and VR3 is used to adjust the maximum temperature.
- VR4 TRIMPOT is used to set the current temperature on LED display.

คุณสมบัติ

- ใช้ไฟเบรกงจ 12 โวลท์ซึ่ง ใช้กระแสสูงสุดประมาณ 250 มิลลิแอมป์
- สามารถใช้กับโหลดได้สูงสุด 500 วัตต์
- ตัวเซ็นเซอร์ สามารถวัดอุณหภูมิได้ตั้งแต่ -20°C ไปจนถึง +100°C
- หน้าจอแสดงผล สามารถแสดงผลได้ 3 1/2 หลัก (ความละเอียดในการแสดงผล 0.1°C)

- หน้าจอแสดงผลได้ 3 สถานะ คือ
 - 1) อ่านอุณหภูมิปกติ
 - 2) ตั้งค่าอุณหภูมิสูงสุด
 - 3) ตั้งค่าอุณหภูมิต่ำสุด
- สามารถกำหนดให้วางทำงานที่อุณหภูมิสูงหรืออุณหภูมิต่ำได้
- เมื่อ LED บอกสถานะการทำงานของรีเลย์และวงจร
- สามารถปรับจุดการทำงานและหยุดการทำงานของรีเลย์ได้

จุดต่อและจุดปรับแต่ง

- จุด 12V ใช้สำหรับต่อแหล่งจ่ายไฟขนาด 12 โวลท์ซึ่ง
- จุด SENSOR ใช้สำหรับต่อเซ็นเซอร์อุณหภูมิ
- จุด NC, COM, NO ใช้สำหรับต่ออุปกรณ์ที่ต้องการจะควบคุม
- สวิตช์ SW1 ใช้ในการปรับการแสดงผลของหน้าจอแสดงผล
 - ตำแหน่ง A ใช้สำหรับแสดงค่าของอุณหภูมิปัจจุบัน ที่ตัวเซ็นเซอร์วัดได้
 - ตำแหน่ง B ใช้สำหรับแสดงค่าของอุณหภูมิที่ต้องการทำงาน
 - ตำแหน่ง C ใช้สำหรับแสดงค่าของอุณหภูมิต่ำ
- จ้มปอร์ J1 ใช้สำหรับเลือกจุดการทำงานของวงจร ถ้าเข้าที่จุด INV วงจร จะทำงานที่อุณหภูมิต่ำแล้วตัดที่อุณหภูมิสูง ถ้าเข้าที่จุด NOR วงจรจะทำงานที่อุณหภูมิสูงแล้วตัดที่อุณหภูมิต่ำ
- VR1 ใช้ในการปรับตั้งอุณหภูมิต่ำ
- VR2 และ VR3 ใช้ในการปรับตั้งอุณหภูมิสูง โดย VR2 จะเป็นตัวปรับละเอียดและ VR3 จะเป็นตัวปรับขยาย
- VR4 TRIMPOT ใช้สำหรับปรับตั้งหน้าจอแสดงผล ให้ตรงกับที่ตัวเซ็นเซอร์อ่านได้


- VR5 is setting the voltage at pin 36 of IC2 to 100mV.

ADJUSTMENT FOR FIRST TIME


- 1.Apply 12V power to "12V" point. LED POWER is light on.
- 2.Connect the potentiometer of 10K to "SENSOR" point. Adjust the a DC voltage range. Connect the multimeter to "SENSOR" point. Adjust the potentiometer until the voltage measured is 2.980V.
- 3.Connect the multimeter to pin 36 of IC2. Adjust VR5 5K until the voltage measured is 100mV.
- 4.Slide SW1 to "A" position.
- 5.Adjust VR4 TRIMPOT until LED display showing to "25.0".
- 6.Disconnect the temperature sensor to "SENSOR" point. LED display is showing to the current temperature.

SETTING THE OPERATION

- 1.Set J1 jumper ("INV" point is operation to minimum temperature and "NOR") point is operation to maximum temperature.
- 2.Apply 12V power to "12V" point. LED POWER is light on.
- 3.Slide SW1 to "B" position. Adjust VR2 and VR3 to set the maximum temperature and read the temperature on LED display.
- 4.Slide SW1 to "C" position. Adjust VR1 to set the minimum temperature and read the temperature on LED display.
- 5.Slide SW1 to "A" position. LED display is showing to the current temperature. If you set J1 jumper to "NOR" point, when the temperature more than the setting in the maximum temperature mode at the relay is work and LED RY is light on. But when the temperature less than the setting in the minimum temperature at the relay is not work and LED RY is light off. But if you set J1 jumper to "INV" point, the operation will to alternate with the "NOR" point.



CIRCUIT DIAGRAM



NO.1